Thompson Knolls Cu-Au-Mo Porphyry Project

Summary of TK-3 drillhole



Sergei Diakov
based on field notes from
project geologist
Miguel Bernardo

November 2021

Disclaimer

Disclaimer

BCM Resources Corporation is an early stage mineral resource exploration company with no mineral projects that have been proven to be economic. The Thompson Knolls property is distinct and separate from any adjacent property, including Kings Canyon and Bingham, and the issuers, Inland and BCM Resources, stress that there is no contained inference herein that Issuers will obtain similar information or similar forms or grades of mineralization from the Thompson Knolls property.

The drill hole sample assays presented herein are from historical drilling data which pre-dates NI 43-101, and most of the assays were performed by a Centurion Mines Corporation, a professional mining company, assay laboratory set up and staffed by a professional assayer. The high grade drilling assay samples from drill hole CKC-96-10 were re-assayed for gold and silver by Centurion in 1996 at a professional, IDSO 9000 certified assay laboratory. As such, the early assay data and sampling and assaying procedures are historical and should be viewed in that context. The historical drilling programs were conducted under the supervision of a person who is a Qualified Person. All of the post 1996 rock chip geochemical analyses were performed by certified assay labs. As such, the historical sampling, assaying and QA/QC protocols are not known, and therefore these results must also be seen and interpreted in an historical context. These data are presented here for historical information purposes only. These data have been studied and verified and felt to be appropriate at this early stage of this exploration project by Richard R. Redfern, QP, who has written a 43-101 technical report on the property and these assay and sampling programs.

The contents of this presentation, including the historical information contained herein, are for informational purposes only and do not constitute an offer to sell or a solicitation to purchase any securities referred to herein.

Forward looking statements

This presentation includes certain forward-looking statements about future events and/or financial results which are forward looking in nature and Subject to risks and uncertainties. Forward-looking statements include without limitation, statements regarding the company's plans, goals or objectives and future completion of mine feasibility studies, mine development programs, capital and operating costs, production, potential mineralization and reserves, exploration results and future plans and objectives of Inland. Forward-looking statements can generally be Identified by the use of forward-looking terminology such as "may," "will,", "expect," "intend," "estimate," "anticipate," "believe," or "continues" or the negative thereof or variations thereon or similar terminology. There can be no assurance that such statements will prove to be accurate and actual results and future events could differ materially from those anticipated in such statements. Important factors that could cause actual results to differ materially from expectations include risks associated with mining generally and pre-development stage projects in particular including but not limited to changes in general economic conditions, litigation, legislative, environmental and other judicial, regulatory, technological and operational difficulties, labor relations matters, foreign exchange costs & rates. Potential investors should conduct their own investigations as to the suitability of investing in securities of Inland and BCM Resources.

Drillhole Section

- 0-1,452ft – fanglomerate cover
- 1,452ft – contact between fanglomerate and brecciated red colored dolomite
- 1,452-1,874ft – intensely deformed rocks of brecciated dolomites and clays – fault zone
- 1,874ft – green clay contact with brecciated red colored dolomite
- 1,874-1,878ft – section of clays
- 1,878ft – top of altered mineralized quartz-monzonite porphyry
- 2,037ft – bottom of TK-21-3 drillhole closed due to drilling failure

Marbleized dolomite with numerous oxidized quartz-calcite veinlets

Brecciated dolomite fragments cemented by quartz-calcite partly oxidized with pyrite-chalcopyrite mineralization

Amount of sulfides:

pyrite	~ 3 vol %
chalcopyrite	~ 3 vol%

Note:
Circles in black indicate Niton XRF measurement spots. Not included here pending assay results



Dolomite with multiple differently oriented calcite veins carrying pyrite and chalcopyrite mineralization

Amount of sulfides:

pyrite	~ 10 vol%
chalcopyrite	~ 4 vol%

Note:
Circles in black indicate Niton XRF measurement spots. Not included here pending assay results

Intrusive porphyry with quartz-sericite-pyrite alteration carrying disseminated (partly oxidized) sulfides

Quartz hairline veinlets contain pyrite, chalcopyrite and molybdenite

Amount of sulfides:

pyrite	~ 2 vol%
chalcopyrite	~ 1 vol%
molybdenite	~ 1 vol%

Note:
Circles in black indicate Niton XRF measurement spots. Not included here pending assay results

Altered quartz-monzonite porphyry with K-feldspar

Quartz veinlet carries inclusions of pyrite and molybdenite

Amount of sulfides:

molybdenite	~ 2 vol %
pyrite	~ 1 vol %

Note:
Circles in black indicate Niton XRF measurement spots. Not included here pending assay results

Quartz molybdenite vein and veinlets in altered quartz-monzonite porphyry

Amount of sulfides:

molybdenite	~ 3 vol%
pyrite	~ 2 vol%
chalcopyrite	~ 1 vol%

Note:
Circles in black indicate Niton XRF measurement spots. Not included here pending assay results

Quartz-monzonite porphyry with intense quartz-sericitic alteration and disseminated sulfide mineralization

Randomly oriented quartz sulfide veinlets. Note sub perpendicular to core axis vein filled with massive molybdenite-pyrite-chalcopyrite

Amount of sulfides:

molybdenite	~ 3 vol%
pyrite	~ 2 vol%
chalcopyrite	~ 1 vol%

Note:
Circles in black indicate Niton XRF measurement spots. Not included here pending assay results


END